






1. REMOVE PARTING LINES & EXTRA MATERIAL FROM TOGGLE & ROTARY LOCK LIFT HOLES BEFORE ASSEMBLY.
2. WELDING SHOULD BE UNIFORM AND OF GOOD QUALITY.

02	Drawing improvement (RED-RD-CS-02-ECN-10-20)							Bhaskara Rao K		30.11.20										
01	AS PER ECN NO. RED-RD-CS-02-ECN-01-20							Bhaskara Rao K		12.03.20										
00	INITIAL DRAWING RELEASE							Sudhir		11.12.13		03	Drawing Template updated Escorts to Sona						06.03.26	
Alt.	Amendments							Name	Sign	Date	Alt.	Amendments				Name	Sign	Date		
Sur.Sym.	N1	N2	N3	N4	N5	N6	N7	N8	N9	N10	N11	N12	Mat.-					-		
Ra Value (µm)	0.025	0.05	0.1	0.2	0.4	0.8	1.6	3.2	6.3	12.5	25	50	Sur. Treat.-					-		
IS:3073	REF. NO.:-											-	Size -			-	Wt.	6.0	kg. Appx.	

Gen. Tol. : IS-2102						Scale	 SONA COMSTAR SONA BLW Precision Forgings Limited Railway Business Plot No. 114-115, Sector-24, Faridabad-121005	
	Fine	Med.	Coar.	Very Coar.				
0.5-3	±0.05	±0.1	±0.2	--		Dimensions in mm		
>3-6	±0.05	±0.1	±0.3	±0.5				
>6-30	±0.10	±0.2	±0.5	±1.0				
>30-120	±0.15	±0.3	±0.8	±1.5				
>120-400	±0.2	±0.5	±1.2	±2.5				
>400-1000	±0.3	±0.8	±2.0	±4.0	Title ROTARY LOCK LIFT ASSY	Drawing No. SK-1656	Sheet 1 of 1 Alt No. 02	
>1000-2000	±0.5	±1.2	±3.0	±6.0				
>2000-4000	-	±2.0	±4.0	±8.0				
Project :- AAR-H COUPLER								Status: Draft Drawing