

 ESCORTS RAILWAY EQUIPMENT DIVISION		CHANGE REQUEST SHEET	
Department	R&D	CRS No.	RED-RD-DS-001-CRS-R&D-03-20
Project	LHB PLUG DOOR	Date	28-07-20
Component Description:	GUARD PANEL HOUSING, STICKER FOR GUARD PANEL, DOOR PANEL WITH HOUSINGS ASSEMBLY-1, INNER SKIN FOR DOOR LEAF-1, BOTTOM GUIDE RAIL		
Item Code:	1E1S100000335, 1E1S100000363, 1E1S100000486, 1E1S100000400, 1E1S100000051		
Drawing No. & Rev.	1S100000335 (Rev 00), 1S100000363 (Rev 00), 1S100000486 (Rev 00), 1S100000400 (Rev 00), 1S100000051 (Rev 02).		
Changes requested:	1S100000335: - • Reduce the size of GP from 500x700X250 to 500x400x200. • Add cutout for HMI, and connectors. • Change position of cutouts, & add cutout for HMI in the Door as per the latest RDSO specification. • Add cutouts in the Mounting Plate for connectors. 1S100000363: - • Reduce the size of sticker as per the new size of GP. • Change position of cutouts as per the latest RDSO specification. 1S100000486: - Modify the design by adding a part for mounting the leading edge passive door seal. 1S100000400: - Add holes for bolting the leading edge passive door seal. 1S100000051:- Change the dim. 79 to 53.		
Reason for Change:	1S100000335: - Design of Guard Panel is standardized in the latest specification released by RDSO for Automatic Plug Doors. 1S100000363: - Design of Guard Panel is standardized in the latest specification released by RDSO for Automatic Plug Doors. 1S100000486: - Door panel requires a passive seal at leading edge for proper sealing. 1S100000400: - Door panel requires a passive seal at leading edge for proper sealing. 1S100000051:- Position of holes to be modified to make them symmetric about the door panel.		
Impact Analysis:	Cost	Obsolescence	
	N.A.	N.A.	
Feasibility Analysis:	It is Feasible.		
Risk*:	No		
Action by R&D:	Revise the drawings of Guard Panel Housing & Sticker for Guard Panel, Door Panel with Housings Assembly-1, & Inner Skin for Door Leaf -1, Bottom Guide Rail.		
Documents Affected	1S100000335 (Rev 00), 1S100000363 (Rev 00), 1S100000486 (Rev 00), 1S100000400 (Rev 00), 1S100000051 (Rev 02).		
Remarks:-			

* If Risk is high then Root Cause Analysis to be conducted.

S.S. Initiated By	C.V.K. Checked By	K.B.R Approved By	Sheet : 1 Of Sheets : 1
----------------------	----------------------	----------------------	-------------------------------