## <u>Value Stream Map – Event #3</u> Customer LeanMan Factory **Product** Zoom Zoom Cars **Demand** 3/4.00mins **Improvement TAKT** 1.33 mins NVA changed because fixture handling is eliminated and **Future State** inspection is moved into the cell. Drops from 0.5 to 0.2 Quality nonconforming material still poses a threat to flow 1-pc Pull w/ kanban VA time reduced from 3.6 to 3.05 control Work Cell Simulation exercise To run the LeanSim simulation exercises in a continuous loop, the finished cars are disassembled and the raw materials returned to the 'supplier' stage. This can be performed by the 'planner' or by other participants in the exercise **Production Planning** Customer Forecast Supplier Order supply 6 sets of each Pack & Ship Schedule 3 Cars Every item every 8 4 minutes minutes $\infty$ $\infty$ Work Cell Operators in Close Proximity 4 Subs Max 1 Kit Max Department #1 Department #4 1 Car Max Department #5 Department #2 Department #3 Car Max Department #6 3 Cars Max 1 car body Kit Jobs Detail - optional Inspect Final Assembly FG / Shiptable Subassembly Withdrawal Withdrawal Withdrawal Withdrawal Withdrawal 0.30 mins 0.20 mins 0.30 mins 0.50 mins 0.05 mins 1.00 mins MT 0.50 mins MT 0.30 mins МТ MT 0.50 mins MT 0.05 mins 0.30 mins MT 0.10 mins 0.00 mins ΑT 0.00 hrs AT 0.00 mins AT ΑT 0.00 mins AT 0.00 mins ΑT 0.00 mins CO 0.10 mins CO 0.10 mins CO 0.10 mins CO 0.10 mins CO 0.00 mins CO 0.00 mins YLD YLD 66.70% 100.00% YLD 100.00% YLD 67.00% YLD 67.00% YLD 100.00% Wheel 80.00=0.44d \$0.00 Axle 80.00=0.44d \$0.00 Brake Disk 80.00=0.44d \$0.00 Car Body 20.00=0.44d \$0.00 Totes & Bags Rework Rework Mtl 0.00 mins 0.20 mins 0.00 mins 0.00 mins 0.00 mins NVA 0.20 mins VA 3.05 mins 0.50 mins 1.00 mins 1.00 mins 0.50 mins 0.05 mins