



Carbon (C)

$$6x_1 = x_4 + x_5$$

Nitrogen (N)

$$x_2 = 0.2 x_4$$

H

$$12x_1 + 3x_2 = 1.8x_4 + 2x_6$$

O

$$6x_1 + 2x_3 = 0.5x_4 + 2x_5 + x_6$$

$$\begin{bmatrix} 6 & 0 & 0 & -1 & -1 & 0 \\ 0 & 1 & 0 & -0.2 & 0 & 0 \\ 12 & 3 & 0 & -1.8 & 0 & -2 \\ 6 & 0 & 2 & -0.5 & -2 & -1 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \\ x_3 \\ x_4 \\ x_5 \\ x_6 \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \\ 0 \\ 0 \end{bmatrix}$$