












IMU 추적 QC — FR5 teleop 프로빙 블록 'probe' · chip

회색 띠 = 오른쪽 확대 구간



판정		
정렬 잔차 RMS	0.00 / 3	통과
동적 각오차 RMS (지연보정)	0.00 / 2	통과
회전 실패 지연	24.98 / 50	통과
상호상관 최소	1.00 / 0.99	통과
heading(spin) 드리프트	0.00 / 1	통과
변위 오차 1 s 창 (C)	7.24 / 2	불합격
변위 오차 2 s 창 (C)	9.72 / 5	불합격
100 mm 이동 상대오차 (D, 검증)	4.02 / 3	불합격