Assignment 1 – SMART HOME

```
int t=2;
int e=3;
void setup()
Serial.begin(9600);
pinMode(t,OUTPUT);
pinMode(e,INPUT);
pinMode(12,OUTPUT);
void loop()
//ultrasonic sensor
digitalWrite(t,LOW);
digitalWrite(t,HIGH);
delayMicroseconds(10);
digitalWrite(t,LOW);
float dur=pulseIn(e,HIGH);
float dis=(dur*0.0343)/2;
Serial.print("Distance is: ");
Serial.println(dis);
 //LED ON
if(dis>=100)//(in terms of centimeter)
 digitalWrite(8,HIGH);
 digitalWrite(7,HIGH);
 //Buzzer For ultrasonic Sensor
if(dis > = 100)
for(int i=0; i<=30000; i=i+10)
 tone(12,i);
 delay(1000);
 noTone(12);
 delay(1000);
 //Temperate Sensor
 double a= analogRead(A0);
 double t=(((a/1024)*5)-0.5)*100;
 Serial.print("Temp Value: ");
 Serial.println(t);
 delay(1000);
```

```
//LED ON
if(t \ge 100) //(in terms of celsius)
digitalWrite(8,HIGH); digitalWrite(7,HIGH);
//Buzzer for Temperature Sensor
if(t \ge 100)
{
for(int i=0; i<=30000; i=i+10)
tone(12,i);
delay(1000);
noTone(12);
delay(1000);
//LED OFF
if(t<100)
digitalWrite(8,LOW);
digitalWrite(7,LOW);
}
```



