Axis	Sign Convention
X-axis, body axes	Positive: Forward
Y-axis, body axes	Positive: Right
Z-axis, body axes	Positive: Down
Surface	Sign Convention
L_ail	Positive: Trailing Edge Down
R_ail	Positive: Trailing Edge Down
L_spoiler	Positive: Trailing Edge Up
R_spoiler	Positive: Trailing Edge Up
elevator	Positive: Trailing Edge Down
rudder	Positive: Trailing Edge Left
stab	Positive: Trailing Edge Down
flap	Positive: Trailing Edge Down
Command	Sign Convention
Aileron Cmd, δ_a	Positive: Right TE Down, Left TE Up, $\delta_a = (\delta_{aR} - \delta_{aL})$
Spoiler Cmd, δ_s	Positive: Right TE Up, Left TE Up, $\delta_s = (\delta_{sR} + \delta_{sL})$
Throttle Cmd	$0 \Rightarrow \text{Idle Thrust}, 100 \Rightarrow \text{Full Thrust}$
geardown	$0\Rightarrow$ gear stowed, $1\Rightarrow$ gear down
Wind Velocity	Sign Convention
NorthWind	Positive: From the North
EastWind	Positive: From the East
VerticalWind	Positive: Rising Air