
(a) DAC Transfer Linearity
Ideal Linear (R^2=1.0)
Physical Measurement (R^2=0.9998)
Physical Voltage (V)
Commanded Setpoint (C)
0.0
0.5
1.0
1.5
2.0
2.5
3.0
0
10
20
30
40
50
(b) Absolute Error (|Delta T| <= 0.5 C)
Reconstruction Error (C)
Commanded Setpoint (C)
0.6
0.4
0.2
0.0
−0.2
−0.4
−0.6