```
#include "dht.h"
#define dataPin 2
dht DHT;
int temp;
int hum;
void setup() {
  Serial.begin(9600);
 delay(2000); // Wait for the DHT sensor to stabilize
}
void loop() {
  int readData = DHT.read11(dataPin);
  hum = DHT.humidity;
  temp = DHT.temperature;
  // Output data formatted for Serial Plotter
  Serial.print(hum); // Humidity
  Serial.print(","); // Separator
  Serial.println(temp); // Temperature
  delay(1000); // Wait 1 second before next reading
}
```