

$$x = \sqrt{\frac{y}{y}}, y = \sqrt{\frac{gedreht}{R_z 16}}$$

$$y = \sqrt{\frac{R_z 16}{R_z 4}}$$

$$teinstgedreht$$

$$z = \sqrt{\frac{R_z 4}{R_z 4}}$$

unbemaßte Fasen 1x45°