





1. Modulus of Plasticity is equal to PERCENTAGE PASSING X PLASTICITY INDEX
2. WE NEED TO ADD A BUTTON WHERE ONE CAN CLICK AND THE SOILS ARE CLASSIFIED AS NON PLASTIC- (SEE HOW YOU DID ON PSD) – THIS IS HOW IT LOOKS LIKE WHEN CLASSIFIED AS NON PLASTIC



THIS NORMALLY HAPPENS WHEN SHRINKAGE IS 0.00 AND PI IS ZERO- NORMALLY WE DON'T KEY ANYTHING ON PLASTIC LIMIT- WE JUST DISPLAY AS NON – PLASTIC (THIS WHERE I AM PROPOSING YOU CREATE A BUTTON FOR THIS.