

Arista Access Switch - Alarm Resolution SOP for ALARM_1876

Node: Arista-Access-Bangalore-KA-72 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_1876

Description

This SOP outlines the steps to diagnose and resolve the ALARM_1876 issue on the Arista Access Switch Node ID: Arista-Access-Bangalore-KA-72

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Misconfiguration	Medium
Environmental Issues	Low

Diagnostic Commands

```
show system internal switch
show system internal hardware
show system internal software
show system internal environment
show alarm detail
```

Resolution Steps

- Step 1: {'Step': '1. Check for hardware failure', 'Action': "Run the command 'show system internal hardware' to check for any hardware issues"}
- Step 2: {'Step': '2. Check for software misconfiguration', 'Action': "Run the command 'show system internal software' to check for any software issues. If any issues are found, reboot the switch and reapply the configuration"}
- Step 3: {'Step': '3. Check for environmental issues', 'Action': "Run the command 'show system internal environment' to check for any environmental issues. If any issues are found, rectify the issue and reboot the switch"}
- Step 4: {'Step': '4. Clear the alarm', 'Action': "Run the command 'clear alarm' to clear the ALARM_1876"}
- Step 5: {'Step': '5. Verify the fix', 'Action': "Run the command 'show alarm detail' to verify that the ALARM_1876 has been cleared"}

Post-Check Verification

```
show system internal switch
show system internal hardware
show system internal software
show system internal environment
show alarm detail
```