

Arista Access Switch Alarm SOP - ALARM_4753

Node: Arista-Access-Bangalore-KA-72 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_4753

Description

This SOP outlines the steps to diagnose and resolve minor alarm ALARM_4753 on Arista Access Switch Node ID: Arista-Access-Bangalore-KA-72.

Potential Root Causes

Cause	Probability
Inconsistent configuration on the switch	Medium
Hardware failure or degradation	Low
Interoperability issues with neighboring devices	High

Diagnostic Commands

```
show system resources
show interface status
show version
show log messages | include ALARM_4753
```

Resolution Steps

- Step 1: {'Step': 'Check the switch configuration for inconsistencies', 'Action': "Verify the switch configuration using 'show running-config' command and correct any discrepancies."}
- Step 2: {'Step': 'Check for hardware issues', 'Action': "Perform a hardware inspection and run 'show system resources' command to check for any hardware-related issues."}
- Step 3: {'Step': 'Check for interoperability issues', 'Action': "Verify the configuration of neighboring devices and run 'show interface status' command to check for any connectivity issues."}
- Step 4: {'Step': 'Reload the switch', 'Action': "Reload the switch using 'reload' command to see if the issue resolves."}
- Step 5: {'Step': 'Collect logs and system resources', 'Action': "Collect system logs and system resources using 'show log messages' and 'show system resources' commands to provide to the NOC team for further analysis."}

Post-Check Verification

```
show system resources
show interface status
```

```
show version
```

```
show log messages | include ALARM_4753
```