

Arista Access Switch Node KA-78 Bangalore Alarm 4128 SOP

Node: Arista-Access-Bangalore-KA-78 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_4128

Description

This SOP outlines the procedures for diagnosing and resolving the ALARM_4128 on the Arista Access Switch Node KA-78 Bangalore.

Potential Root Causes

Cause	Probability
Incorrect VLAN configuration	High
Faulty switch firmware	Medium
Hardware issue with the switch	Low

Diagnostic Commands

```
show vlan
show interface status
show version
show boot
debug hardware
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': "Run the 'show vlan' command to check the VLAN configuration.", 'CLI_Command': 'show vlan'}
- Step 2: {'Step': 'Check for firmware updates', 'Action': "Run the 'show version' command to check the firmware version.", 'CLI_Command': 'show version'}
- Step 3: {'Step': 'Perform switch shutdown and restart', 'Action': 'Shut down the switch and then restart it.', 'CLI_Command': 'shutdown\nstartup'}
- Step 4: {'Step': 'Check for hardware issues', 'Action': "Run the 'show interface status' command to check for any hardware issues.", 'CLI_Command': 'show interface status'}

Post-Check Verification

```
show vlan
show interface status
```

```
show version
```

```
show boot
```