

Arista-Access-Bangalore-KA-78 SOP for ALARM_8835

Node: Arista-Access-Bangalore-KA-78 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_8835

Description

ALARM_8835: Major Alarm Triggered on Arista-Access-Bangalore-KA-78 Access Switch.

Potential Root Causes

Cause	Probability
Misconfigured VLAN	High
Faulty SFP Module	Medium
Software Bug	Low

Diagnostic Commands

```
show vlan
show interfaces status
show sfp detail
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': "Run 'show vlan' command to check VLAN configuration"}
- Step 2: {'Step': 'Replace faulty SFP module (if applicable)', 'Action': "Run 'no shutdown' command on the interface after replacing the SFP module"}
- Step 3: {'Step': 'Upgrade software (if applicable)', 'Action': "Run 'no shutdown' command on the interface after upgrading the software"}

Post-Check Verification

```
show vlan
show interfaces status
show sfp detail
show tech-support
```