

Standard Operating Procedure for Arista Access Switch Alarm ALARM_2590 in Bangalore KA-82 Location

Node: Arista-Access-Bangalore-KA-82 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_2590

Description

Alarm ALARM_2590 indicates a critical issue with the Arista Access Switch in Bangalore KA-82 location. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware failure due to power supply issue	High
Software bug or configuration error	Medium
Environmental factors such as temperature or humidity	Low

Diagnostic Commands

```
show system resources
show environment
show power supplies
show software image version
show configuration
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch', 'Description': 'Turn off the switch, wait for 30 seconds, and then turn it back on.', 'CLI_Command': 'reload'}
- Step 2: {'Step': 'Verify power supply status', 'Description': 'Check the power supply status using the show power supplies command.', 'CLI_Command': 'show power supplies'}
- Step 3: {'Step': 'Check software image version', 'Description': 'Verify the software image version using the show software image version command.', 'CLI_Command': 'show software image version'}
- Step 4: {'Step': 'Check configuration', 'Description': 'Verify the configuration using the show configuration command.', 'CLI_Command': 'show configuration'}
- Step 5: {'Step': 'Replace faulty hardware', 'Description': 'If the issue persists, replace the faulty hardware.', 'CLI_Command': ''}

Post-Check Verification

```
show system resources
show environment
show power supplies
show software image version
show configuration
```