

Standard Operating Procedure: Resolving ALARM_5247 on Arista-Access-Bangalore-KA-82

Node: Arista-Access-Bangalore-KA-82 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_5247

Description

Warning: ALARM_5247 on Arista-Access-Bangalore-KA-82 indicating a potential issue with the switch's configuration or hardware. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured VLANs	High
Faulty Ethernet Interfaces	Medium
Overheating or power issues	Low

Diagnostic Commands

```
show interface status
show vlan
show environment
show system resource utilization
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Verify VLAN configuration and ensure it matches the network design', 'CLI_Commands': 'show vlan; show interface status'}
- Step 2: {'Step': 2, 'Action': 'Check for any faulty Ethernet interfaces and replace if necessary', 'CLI_Commands': 'show interface status'}
- Step 3: {'Step': 3, 'Action': 'Check for overheating or power issues and address if necessary', 'CLI_Commands': 'show environment'}
- Step 4: {'Step': 4, 'Action': 'Save the configuration and restart the switch if necessary', 'CLI_Commands': 'save config; reboot'}

Post-Check Verification

```
show interface status
show vlan
```

```
show environment
```

```
show system resource utilization
```