

Arista-Access-Bangalore-KA-82 Minor Alarm SOP for ALARM_9329

Node: Arista-Access-Bangalore-KA-82 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_9329

Description

Troubleshooting procedure for Minor alarm ALARM_9329 on Arista Access Switch Arista-Access-Bangalore-KA-82.

Potential Root Causes

Cause	Probability
Physical Interface Failure	High
Cable Damage or Misconnection	Medium
Switch Software Bug	Low

Diagnostic Commands

```
show interface status
show interface detail
show log | grep ALARM_9329
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check Physical Interface and Connections', 'Description': 'Verify all connections to the interface are secure and not damaged.', 'Commands': 'show interface status'}
- Step 2: {'Step': 'Verify Interface Configuration', 'Description': 'Check the interface configuration for any errors or misconfigurations.', 'Commands': 'show running-config | include interface'}
- Step 3: {'Step': 'Reset the Interface', 'Description': 'Reset the interface to its default state.', 'Commands': 'clear counters interface '}

Post-Check Verification

```
show interface status
show interface detail
show log | grep ALARM_9329
```