

Arista 7250X Access Switch Alarm SOP - ALARM_7199

Node: Arista-Access-Chennai-TN-90 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_7199

Description

This SOP outlines the steps to identify, diagnose, and resolve the ALARM_7199 minor alarm on the Arista 7250X Access Switch in the Chennai-TN-90 location.

Potential Root Causes

Cause	Probability
Incorrect configuration or mismatched switch profiles	High
Software or firmware issues	Medium
Hardware malfunctions (rare)	Low

Diagnostic Commands

```
show system internal alarm
show system internal switch-profile
show hardware
show version
show system internal debug
```

Resolution Steps

- Step 1: {'Step': 'Verify the switch profiles and configuration', 'CLI_Commands': 'show system internal switch-profile'}
- Step 2: {'Step': 'Check for software or firmware issues', 'CLI_Commands': 'show version, show system internal debug'}
- Step 3: {'Step': 'Run the 'clear system internal alarm' command to reset the alarm', 'CLI_Commands': 'clear system internal alarm'}
- Step 4: {'Step': 'Verify the alarm is cleared', 'CLI_Commands': 'show system internal alarm'}

Post-Check Verification

```
show system internal alarm
show system internal switch-profile
show hardware
```

```
show version
```