

Arista Access Switch Alarm Resolution SOP

Node: Arista-Access-Chennai-TN-90 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_7825

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7825 on the Arista Access Switch in Chennai, TN, Node ID: Arista-Access-Chennai-TN-90.

Potential Root Causes

Cause	Probability
Port Loopback or cable issues	High
Switching Table Corruption	Medium
Misconfigured VLANs or VTP	Low

Diagnostic Commands

```
show interface status
show vlan
show vtp status
show spanning-tree detail
```

Resolution Steps

- Step 1: {'Step': '1. Check for port loopback or cable issues', 'Action': "Execute the command 'show interface status' and verify the port status."}
- Step 2: {'Step': '2. Clear switching table corruption', 'Action': "Execute the command 'clear switching-table' and verify the resolution."}
- Step 3: {'Step': '3. Verify VLAN configuration and VTP settings', 'Action': "Execute the commands 'show vlan' and 'show vtp status' to verify correct configuration."}
- Step 4: {'Step': '4. Verify STP configuration and settings', 'Action': "Execute the command 'show spanning-tree detail' to verify correct configuration."}

Post-Check Verification

```
show alarm
show interface status
show vlan
show vtp status
```

```
show spanning-tree detail
```