

Arista Access Switch ALARM_8485 SOP

Node: Arista-Access-Chennai-TN-90 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_8485

Description

This SOP outlines the steps to troubleshoot and resolve a Major ALARM_8485 on the Arista Access Switch Node ID: Arista-Access-Chennai-TN-90. The alarm is indicative of a critical issue and requires immediate attention.

Potential Root Causes

Cause	Probability
Physical Interface Failure	High
Cable or Connector Issue	Medium
Incorrect Configuration	Low

Diagnostic Commands

```
show interfaces detail
show cable-diagnostics tdr interface
show spanning-tree summary
show mac address-table
```

Resolution Steps

- Step 1: {'Step': 'Physical Interface Inspection', 'Description': 'Inspect the physical interface and cable for any signs of damage or degradation.', 'Action': 'Physically inspect the interface and cable'}
- Step 2: {'Step': 'Replace Cable or Connector', 'Description': 'Replace the cable or connector if a physical issue is detected.', 'Action': 'Replace the cable or connector and verify the interface is up'}
- Step 3: {'Step': 'Verify Configuration', 'Description': 'Verify the interface configuration is correct and matches the intended design.', 'Action': 'show run | include and verify the configuration'}
- Step 4: {'Step': 'Reset Interface', 'Description': 'Reset the interface to its defaults and reconfigure it.', 'Action': 'interface no shutdown and no command followed by a show interfaces detail'}

Post-Check Verification

```
show interfaces detail
show cable-diagnostics tdr interface
show spanning-tree summary
show mac address-table
```