

Standard Operating Procedure for Resolving ALARM_9133 on Arista-Access-Chennai-TN-90

Node: Arista-Access-Chennai-TN-90 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_9133

Description

Arista-Access-Chennai-TN-90 is experiencing a Major alarm due to the occurrence of ALARM_9133.

Potential Root Causes

Cause	Probability
Arista-Access-Chennai-TN-90's hardware or software is malfunctioning.	High
Arista-Access-Chennai-TN-90's configuration is incorrect or incomplete.	Medium
Environmental factors are affecting Arista-Access-Chennai-TN-90's operation.	Low

Diagnostic Commands

```
show version
show system resources
show interfaces
show ip traffic
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check the system logs for any error messages or alarms.', 'Action': 'show log'}
- Step 2: {'Step': '"Verify the switch's hardware and software versions."', 'Action': 'show version'}
- Step 3: {'Step': '"Check the switch's configuration for any errors or inconsistencies."', 'Action': 'show running-config'}
- Step 4: {'Step': 'Reboot the switch to see if the issue is resolved.', 'Action': 'reload'}
- Step 5: {'Step': '"Update the switch's firmware to the latest version."', 'Action': 'no shutdown'}
- Step 6: {'Step': '"Check for any environmental factors that could be affecting the switch's operation."', 'Action': 'show environment'}

Post-Check Verification

```
show system resources
show interfaces
```

```
show ip traffic
show log
show tech-support
```