

Arista Access Switch Alarm SOP: ALARM_2312

Node: Arista-Access-Chennai-TN-96 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_2312

Description

This SOP outlines the steps to diagnose and resolve a Major alarm on Arista Access Switch Node ID: Arista-Access-Chennai-TN-96.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Error	Low

Diagnostic Commands

```
show system alarm
show system internal alarm
show hardware
show version
show log
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the switch', 'Description': 'Try to resolve the issue by simply restarting the switch.', 'CLI_Command': 'power reset'}
- Step 2: {'Step': '2. Check and update firmware', 'Description': 'Verify that the switch is running the latest firmware and update if necessary.', 'CLI_Command': 'show version | include Bootloader'}
- Step 3: {'Step': '3. Check and update EOS image', 'Description': 'Verify that the switch is running the latest EOS image and update if necessary.', 'CLI_Command': 'show version | include EOS'}
- Step 4: {'Step': '4. Perform a hardware reset', 'Description': 'If the above steps do not resolve the issue, perform a hardware reset by pressing the reset button.', 'CLI_Command': 'None'}
- Step 5: {'Step': '5. Replace faulty hardware', 'Description': 'If all else fails, replace the faulty hardware.', 'CLI_Command': 'None'}

Post-Check Verification

```
show system alarm
```

```
show system internal alarm
show hardware
show version
show log
```