

Arista Access Switch Alarm SOP: ALARM_7073

Node: Arista-Access-Chennai-TN-96 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_7073

Description

ALARM_7073 is a Major alarm indicating a potential hardware or software failure on the Arista-Access-Chennai-TN-96 switch.

Potential Root Causes

Cause	Probability
Hardware failure	High
Software bug	Medium
Configuration error	Low

Diagnostic Commands

```
show system internal switch-details
show system internal fabric-ports
show system internal routing-table
show version
show log
```

Resolution Steps

- Step 1: {'Step': 'Restart the switch', 'Description': 'Try restarting the switch to see if the issue resolves itself.', 'CLI_Command': 'reboot'}
- Step 2: {'Step': 'Check for hardware failure', 'Description': '"Verify the status of the switch's hardware components."', 'CLI_Command': 'show system internal switch-details'}
- Step 3: {'Step': 'Check for software bug', 'Description': 'Verify the software version and check for any known bugs.', 'CLI_Command': 'show version'}
- Step 4: {'Step': 'Check for configuration error', 'Description': '"Verify the switch's configuration and check for any errors."', 'CLI_Command': 'show configuration'}
- Step 5: {'Step': 'Replace faulty hardware', 'Description': 'If the issue persists, replace the faulty hardware component.', 'CLI_Command': ''}
- Step 6: {'Step': 'Upgrade software', 'Description': 'If the issue persists, upgrade the software to the latest version.', 'CLI_Command': 'archive download-sw /force /overwrite tftp:///euro_mlx_sw.6.5.1.1I3.4.bin'}

Post-Check Verification

```
show system internal switch-details
show system internal fabric-ports
show system internal routing-table
show version
show log
```