

Arista Access Switch Alarm SOP - ALARM_9994

Node: Arista-Access-Chennai-TN-96 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_9994

Description

Alarm ALARM_9994 on Arista Access Switch Arista-Access-Chennai-TN-96 indicates a potential issue with the switch's hardware or software. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Misconfiguration	Low

Diagnostic Commands

```
show system resources
show system internal switch internal
debug hardware errdisable
show version
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch', 'Description': 'Perform a power cycle on the switch to reset its hardware and software components.'}
- Step 2: {'Step': "Check the switch's hardware", 'Description': "Verify that the switch's hardware components are properly seated and connected.", 'CLI_Commands': ['show system resources']}
- Step 3: {'Step': "Check the switch's configuration", 'Description': "Verify that the switch's configuration is correct and up-to-date.", 'CLI_Commands': ['show running-config']}
- Step 4: {'Step': "Upgrade the switch's software", 'Description': "Upgrade the switch's software to the latest version.", 'CLI_Commands': ['upgrade system software package']}

Post-Check Verification

```
show system resources
show system internal switch internal
show version
```