

Arista Access Switch - Alarm Handling SOP: ALARM_1596

Node: Arista-Access-Delhi-NCR-20 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_1596

Description

Alarm Handling Procedure for Arista Access Switch Node ID: Arista-Access-Delhi-NCR-20

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Issue	Medium
Environmental Factors	Low

Diagnostic Commands

```
show system resources
show interfaces status
show log messages
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Isolate the affected port and perform a physical inspection', 'Action': ''}
- Step 2: {'Step': 'Run the 'show log messages' command to identify any error messages related to the alarm', 'Action': 'show log messages | grep ALARM_1596'}
- Step 3: {'Step': 'Attempt to reset the affected port using the 'clear counters' command', 'Action': 'clear counters interface '}
- Step 4: {'Step': 'If the issue persists, perform a software reload using the 'reload' command', 'Action': 'reload'}

Post-Check Verification

```
show interfaces status
show log messages
```