

Arista Access Switch ALARM_2903 SOP

Node: Arista-Access-Delhi-NCR-20 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_2903

Description

This Standard Operating Procedure outlines the steps to identify, diagnose, and resolve the ALARM_2903 issue on the Arista-Access-Delhi-NCR-20 access switch.

Potential Root Causes

Cause	Probability
Incorrect configuration of the switch	Medium
Hardware malfunction or failure	Low
Interoperability issues with other network devices	Low

Diagnostic Commands

```
show switch detail
show system resources
show interface status
show log messages
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Check the switch configuration', 'Action': "Verify the switch configuration using 'show switch detail' command and check for any incorrect settings.", 'CLI_Command': 'show switch detail'}
- Step 2: {'Step': 'Step 2: Check system resources', 'Action': "Verify the system resources using 'show system resources' command and check for any issues.", 'CLI_Command': 'show system resources'}
- Step 3: {'Step': 'Step 3: Check interface status', 'Action': "Verify the interface status using 'show interface status' command and check for any issues.", 'CLI_Command': 'show interface status'}
- Step 4: {'Step': 'Step 4: Check log messages', 'Action': "Verify the log messages using 'show log messages' command and check for any issues.", 'CLI_Command': 'show log messages'}
- Step 5: {'Step': 'Step 5: Reset the switch', 'Action': "Reset the switch using 'reload' command to revert to the default settings.", 'CLI_Command': 'reload'}

Post-Check Verification

```
show switch detail
show system resources
```

```
show interface status  
show log messages
```