

Arista Access Switch - Alarm Resolution SOP for ALARM_1046

Node: Arista-Access-Delhi-NCR-24 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_1046

Description

This SOP outlines the procedures to diagnose and resolve ALARM_1046 on the Arista Access Switch in Delhi NCR.

Potential Root Causes

Cause	Probability
Inconsistent Link State	High
Misconfigured Port Settings	Medium
Hardware Fault	Low

Diagnostic Commands

```
show interface status
show interface detail
show mac address-table
show spanning-tree summary
show environment status
```

Resolution Steps

- Step 1: {'Step': 'Verify link status', 'Action': "Run the command 'show interface status' to verify the link status of the affected interface."}
- Step 2: {'Step': 'Check port settings', 'Action': "Run the command 'show interface detail' to verify the port settings and configuration."}
- Step 3: {'Step': 'Check for hardware faults', 'Action': "Run the command 'show environment status' to check for any hardware faults or issues."}
- Step 4: {'Step': 'Reset the interface', 'Action': "Run the command 'clear interface ' to reset the interface."}

Post-Check Verification

```
show interface status
show interface detail
```

```
show mac address-table  
show spanning-tree summary  
show environment status
```