

Arista Access Switch (Delhi-NCR-24) Minor Alarm Resolution: ALARM_3417

Node: Arista-Access-Delhi-NCR-24 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_3417

Description

This Standard Operating Procedure outlines the steps to diagnose and resolve minor alarm ALARM_3417 on the Arista Access Switch (Delhi-NCR-24).

Potential Root Causes

Cause	Probability
Incorrect configuration of VLAN settings	Medium
Physical loop or incorrect cabling	Low
Hardware issue with the switch	Low

Diagnostic Commands

```
show spanning-tree detail
show vlan
show interfaces status
show mac address-table
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': "Run 'show vlan' command to check for any misconfigured VLANs"}
- Step 2: {'Step': 'Check for physical loops', 'Action': "Run 'show spanning-tree detail' command to detect any physical loops"}
- Step 3: {'Step': 'Verify interface status', 'Action': "Run 'show interfaces status' command to check for any interface errors"}
- Step 4: {'Step': 'Verify MAC address table', 'Action': "Run 'show mac address-table' command to check for any duplicate MAC addresses"}
- Step 5: {'Step': 'Reset VLAN configuration', 'Action': "Run 'clear vlan' command to reset VLAN configuration to default"}
- Step 6: {'Step': 'Verify switch configuration', 'Action': "Run 'show running-config' command to verify switch configuration"}

Post-Check Verification

```
show vlan
show spanning-tree detail
show interfaces status
show mac address-table
```