

Arista-Access-Delhi-NCR-24: ALARM_3687 Major Alarm Resolution SOP

Node: Arista-Access-Delhi-NCR-24 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_3687

Description

This SOP outlines the steps to diagnose and resolve Major Alarm ALARM_3687 on Arista-Access-Delhi-NCR-24, an Arista Access Switch.

Potential Root Causes

Cause	Probability
Link Down	High
Spanning Tree Protocol (STP) issues	Medium
Arista EOS software issues	Low

Diagnostic Commands

```
show interface status
show spanning-tree detail
show mac address-table
show system internal error-buffer
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Verify link status and connectivity using "show interface status" command.'}
- Step 2: {'Step': 2, 'Action': 'Check STP configuration and topology using "show spanning-tree detail" command. Ensure all ports are in the correct state.'}
- Step 3: {'Step': 3, 'Action': 'Clear the MAC address table using "clear mac address-table dynamic" command. Verify the issue is resolved using "show mac address-table" command.'}
- Step 4: {'Step': 4, 'Action': 'Check Arista EOS software version and ensure it is up-to-date. If outdated, upgrade to the latest version.'}
- Step 5: {'Step': 5, 'Action': 'Reset the switch using "reload" command to ensure all configurations are reapplied.'}

Post-Check Verification

```
show interface status
show spanning-tree detail
```

```
show mac address-table  
show system internal error-buffer
```