

Alarm Response Procedure for ALARM_2981 on Arista Access Switch

Node: Arista-Access-Delhi-NCR-30 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_2981

Description

Alarm ALARM_2981 represents a Warning condition on the Arista Access Switch (Node ID: Arista-Access-Delhi-NCR-30).

Potential Root Causes

Cause	Probability
Port Link Down	Medium
SPAN Destination Down	Low
VLAN Configuration Issue	High

Diagnostic Commands

```
show interface status
show spanning-tree detail
show vlan
show mac address-table
```

Resolution Steps

Step 1: {'Step': 'Verify port link status', 'Action': 'Run show interface status command', 'Expected Outcome': 'Port link should be up'}

Step 2: {'Step': 'Check Spanning Tree configuration', 'Action': 'Run show spanning-tree detail command', 'Expected Outcome': 'Spanning Tree should be configured correctly'}

Step 3: {'Step': 'Verify VLAN configuration', 'Action': 'Run show vlan command and verify VLAN database', 'Expected Outcome': 'VLAN configuration should be correct'}

Step 4: {'Step': 'Check for any configuration changes', 'Action': 'Run show run command and verify configuration', 'Expected Outcome': 'No recent configuration changes should be detected'}

Post-Check Verification

```
verify | all
show interface status
show vlan
```

```
show mac address-table
```