

Arista Access Switch Minor Alarm Resolution SOP

Node: Arista-Access-Delhi-NCR-30 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_3870

Description

This SOP outlines the steps to diagnose and resolve the ALARM_3870 minor alarm on the Arista Access Switch Delhi-NCR-30.

Potential Root Causes

Cause	Probability
Interface Flapping	High
Spanning Tree Loop	Medium
Network Congestion	Low

Diagnostic Commands

```
show interface status
show spanning-tree summary
show interface detail
```

Resolution Steps

- Step 1: {'Step': '1. Check Interface Status', 'Description': 'Verify the interface status using the show interface status command.', 'Command': 'show interface status'}
- Step 2: {'Step': '2. Verify Spanning Tree Configuration', 'Description': 'Check the spanning tree configuration using the show spanning-tree summary command.', 'Command': 'show spanning-tree summary'}
- Step 3: {'Step': '3. Clear Spanning Tree Loop', 'Description': 'Clear the spanning tree loop using the clear spanning-tree command.', 'Command': 'clear spanning-tree'}

Post-Check Verification

```
show interface status
show spanning-tree summary
```