

Standard Operating Procedure for Resolving Alarm

ALARM_4993 on Arista Access Switch

Arista-Access-Kolkata-WB-108

Node: Arista-Access-Kolkata-WB-108 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_4993

Description

Alarm ALARM_4993 on Arista Access Switch Arista-Access-Kolkata-WB-108 indicates a Critical issue with the switch hardware or software.

Potential Root Causes

Cause	Probability
Power Supply Failure	High
Overheating of Switch Components	Medium
Software Bug or Configuration Issue	Low

Diagnostic Commands

```
show version
show system power
show environment temperature
show system log | include ALARM_4993
```

Resolution Steps

- Step 1: {'Step': 'Replace faulty Power Supply Unit (PSU)', 'Action': 'Remove the PSU and replace it with a new one. Verify the switch boots up successfully with the new PSU.', 'CLI_Commands': ['no power supply 1', 'power supply 1 insert']}
- Step 2: {'Step': 'Clear Overheat Alarm', 'Action': 'Clear the Overheat alarm on the switch.', 'CLI_Commands': ['no alarm 4993']}
- Step 3: {'Step': 'Reboot the Switch', 'Action': 'Reboot the switch to ensure any software issues are resolved.', 'CLI_Commands': ['reboot']}
- Step 4: {'Step': 'Verify Configuration', 'Action': 'Verify the switch configuration for any software bugs or configuration issues.', 'CLI_Commands': ['show running-config']}

Post-Check Verification

```
show system log | include ALARM_4993
show system power
show environment temperature
```