

Arista Access Switch Node Alarm SOP - ALARM_1701

Node: Arista-Access-Kolkata-WB-110 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_1701

Description

Alarm 1701 is triggered when the system detects a minor issue on Arista-Access-Kolkata-WB-110. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Misconfiguration	Medium
Environmental Factors	Low

Diagnostic Commands

```
show system internal alarm
show system internal log
show environment temperature
show environment humidity
```

Resolution Steps

- Step 1: {'Step': '1. Gather Information', 'Action': 'Run the diagnostic commands to identify the cause of the alarm.'}
- Step 2: {'Step': '2. Check System Logs', 'Action': "Run the command 'show system internal log' to check for any error messages related to the alarm."}
- Step 3: {'Step': '3. Check Temperature and Humidity', 'Action': "Run the commands 'show environment temperature' and 'show environment humidity' to check for any environmental issues."}
- Step 4: {'Step': '4. Restart the System', 'Action': "Run the command 'reboot' to restart the system and see if the alarm clears."}
- Step 5: {'Step': '5. Check for Hardware Issues', 'Action': "Run the command 'show system internal health' to check for any hardware issues."}

Post-Check Verification

```
show system internal alarm
```

```
show system internal log
show environment temperature
show environment humidity
```