

Arista Access Switch Alarm Resolution SOP

Node: Arista-Access-Kolkata-WB-110 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_8451

Description

This SOP outlines the steps to resolve the critical alarm ALARM_8451 on the Arista Access Switch Node ID: Arista-Access-Kolkata-WB-110.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Issue	Low

Diagnostic Commands

```
show system resources
show environment
show log | include ALARM_8451
show interface status
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the switch', 'Description': 'Power cycle the Arista Access Switch to see if the alarm resolves itself.'}
- Step 2: {'Step': '2. Check for hardware issues', 'Description': "Run the diagnostic command 'show system resources' and 'show environment' to check for any hardware issues.", 'Action': 'Replace the faulty hardware if necessary.'}
- Step 3: {'Step': '3. Check for software issues', 'Description': "Run the diagnostic command 'show log | include ALARM_8451' to check for any software-related issues.", 'Action': 'Upgrade or downgrade the software if necessary.'}
- Step 4: {'Step': '4. Check for configuration issues', 'Description': "Run the diagnostic command 'show interface status' to check for any configuration-related issues.", 'Action': 'Correct the configuration if necessary.'}

Post-Check Verification

```
show system resources
```

```
show environment
show log | include ALARM_8451
show interface status
```