

SOP for Resolving Critical Alarm ALARM_9958 on Arista-Access-Kolkata-WB-110

Node: Arista-Access-Kolkata-WB-110 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_9958

Description

A critical alarm indicating a hardware failure or software corruption on the Arista-Access-Kolkata-WB-110 access switch.

Potential Root Causes

Cause	Probability
Hardware failure	High
Incorrect configuration	Medium
Software corruption	Low

Diagnostic Commands

```
show system resource
show switch detail
show version
show log | last 10
show interfaces | exclude up
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Power cycle the switch to reset the hardware and software state.', 'CLI_Command': 'system reboot'}
- Step 2: {'Step': 2, 'Action': 'Check the switch configuration for any errors or inconsistencies.', 'CLI_Command': 'show running-config'}
- Step 3: {'Step': 3, 'Action': 'Verify the switch hardware is functioning correctly.', 'CLI_Command': 'show system resource'}
- Step 4: {'Step': 4, 'Action': 'Clear the switch log to remove any error messages.', 'CLI_Command': 'clear log'}
- Step 5: {'Step': 5, 'Action': 'Reboot the switch to apply any configuration changes.', 'CLI_Command': 'system reboot'}

Post-Check Verification

```
show system resource
show switch detail
show version
show log | last 10
show interfaces | exclude down
```