

Arista Access Switch - ALARM_3859 SOP

Node: Arista-Access-Kolkata-WB-116 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_3859

Description

Standard Operating Procedure for investigating and resolving the ALARM_3859 alarm on Arista Access Switch (Node ID: Arista-Access-Kolkata-WB-116). This alarm indicates a warning level issue.

Potential Root Causes

Cause	Probability
Interface errors due to misconfiguration or hardware failure	High
Software issues with the switch operating system	Medium
Network congestion or oversubscription	Low

Diagnostic Commands

```
show interface status
show interface detail
show system resource
show logging
```

Resolution Steps

- Step 1: {'Step': '1. Check the interface status and detail', 'Action': "Run the command 'show interface status' and 'show interface detail' to identify any interface errors or issues."}
- Step 2: {'Step': '2. Verify system resource utilization', 'Action': "Run the command 'show system resource' to check if the system is experiencing resource constraints."}
- Step 3: {'Step': '3. Check the system logs', 'Action': "Run the command 'show logging' to identify any software issues or errors."}
- Step 4: {'Step': '4. Perform a software reboot', 'Action': "Run the command 'request system reboot' to reboot the switch and resolve any software issues."}
- Step 5: {'Step': '5. Reconfigure the interface', 'Action': "Run the command 'conf t', then 'interface [interface-name]', and finally 'no shutdown' to reconfigure the interface."}

Post-Check Verification

```
show interface status
show interface detail
```

```
show system resource
```

```
show logging
```