

Arista Access Switch Kolkata WB-116 - ALARM_7203

Major Alarm SOP

Node: Arista-Access-Kolkata-WB-116 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_7203

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7203 major alarm on Arista Access Switch Kolkata WB-116.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Configuration Issue	Medium
Environmental Factors (Temperature/Humidity)	Low

Diagnostic Commands

```
show system resources
show hardware
show version
show bootvars
show environment
```

Resolution Steps

- Step 1: {'Step': '1. Check System Resources', 'Action': "Run the command 'show system resources' to check for any resource-intensive processes.", 'CLI_Command': 'show system resources'}
- Step 2: {'Step': '2. Inspect Hardware', 'Action': 'Verify that all hardware components are properly seated and functioning correctly.', 'CLI_Command': ''}
- Step 3: {'Step': '3. Check Software Configuration', 'Action': 'Verify that the switch configuration is correct and not causing any issues.', 'CLI_Command': 'show running-config'}
- Step 4: {'Step': '4. Boot Variables Check', 'Action': 'Verify that the boot variables are set correctly.', 'CLI_Command': 'show bootvars'}
- Step 5: {'Step': '5. Environment Check', 'Action': 'Verify that the environment is within the recommended temperature and humidity range.', 'CLI_Command': 'show environment'}
- Step 6: {'Step': '6. Reboot the Switch', 'Action': 'Reboot the switch to clear any temporary issues.', 'CLI_Command': 'reboot'}

Step 7: {'Step': '7. Verify Alarms', 'Action': 'Verify that the ALARM_7203 major alarm has cleared.', 'CLI_Command': 'show system alarms'}

Post-Check Verification

```
show system alarms
show system resources
show hardware
show version
```