

Arista Access Switch SOP for Alarm ALARM_7274

Node: Arista-Access-Kolkata-WB-116 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_7274

Description

Alarm ALARM_7274 on Arista Access Switch (Node ID: Arista-Access-Kolkata-WB-116) indicates a critical issue. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware failure	High
Software misconfiguration	Medium
Environmental issues (temperature, humidity, etc.)	Low

Diagnostic Commands

```
show system internal switch internal alarms
show system internal switch internal counters
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Check the hardware logs for any fault records', 'Action': 'show system internal switch internal logs'}
- Step 2: {'Step': 'Reboot the switch to clear any software-related issues', 'Action': 'reboot'}
- Step 3: {'Step': 'Verify the environmental conditions and adjust as necessary', 'Action': 'Check temperature, humidity, and other environmental factors'}
- Step 4: {'Step': 'Run a diagnostic test on the affected interface', 'Action': 'test interface '}
- Step 5: {'Step': 'Reconfigure the switch to resolve any software-related issues', 'Action': 'configure replace '}

Post-Check Verification

```
show system internal switch internal alarms
show interface status
show system internal switch internal counters
```