

Standard Operating Procedure for Alarm

ALARM_9183 on Arista Access Switch

Node: Arista-Access-Kolkata-WB-116 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_9183

Description

Alarm ALARM_9183 indicates a potential issue with packet forwarding on Arista-Access-Kolkata-WB-116 Access Switch.

Potential Root Causes

Cause	Probability
Misconfigured VLANs or VLAN mappings	High
Inter-VLAN routing issues	Medium
ARP table overflow or inconsistent ARP entries	Low

Diagnostic Commands

```
show vlan brief
show vlan mapping
show ip arp
show ip route
show interface status
```

Resolution Steps

Step 1: {'Step': 1, 'Description': 'Verify VLAN configurations and mappings', 'CLI_Command': 'show vlan brief'}

Step 2: {'Step': 2, 'Description': 'Resolve inter-VLAN routing issues', 'CLI_Command': 'show ip route'}

Step 3: {'Step': 3, 'Description': 'Clear ARP table and check for inconsistencies', 'CLI_Command': 'clear arp-table'}

Step 4: {'Step': 4, 'Description': 'Verify interface status and packet forwarding', 'CLI_Command': 'show interface status'}

Step 5: {'Step': 5, 'Description': 'Reload the switch if issue persists', 'CLI_Command': 'reload'}

Post-Check Verification

```
show vlan brief
```

```
show ip arp  
show interface status
```