

Arista Access Switch Alarm Handling SOP

Node: Arista-Access-Kolkata-WB-120 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_2255

Description

This SOP outlines the steps to handle ALARM_2255, a Warning severity alarm on the Arista Access Switch, Node ID: Arista-Access-Kolkata-WB-120.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Buffer Memory Overflow	Medium
Software or Firmware Issues	Low

Diagnostic Commands

```
show system resources
show buffer utilization
show processes cpu sort -h
show system redundancy status
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': 'Run show system resources command to verify CPU utilization', 'CLI_Command': 'show system resources'}
- Step 2: {'Step': '2. Verify Buffer Utilization', 'Action': 'Run show buffer utilization command to verify buffer memory overflow', 'CLI_Command': 'show buffer utilization'}
- Step 3: {'Step': '3. Restart the Switch', 'Action': 'Restart the switch to clear any software or firmware issues', 'CLI_Command': 'reboot'}
- Step 4: {'Step': '4. Verify System Redundancy Status', 'Action': 'Run show system redundancy status command to verify system redundancy status', 'CLI_Command': 'show system redundancy status'}

Post-Check Verification

```
show system resources
show buffer utilization
show system redundancy status
```