

Standard Operating Procedure for Resolving ALARM_7441 on Arista-Access-Kolkata-WB-122

Node: Arista-Access-Kolkata-WB-122 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_7441

Description

ALARM_7441 is triggered when the Arista-Access-Kolkata-WB-122 access switch detects a critical hardware failure.

Potential Root Causes

Cause	Probability
Hardware Failure: CPU Over Temperature	High
Hardware Failure: Fan Failure	Medium
Software Issue: Configuration Error	Low

Diagnostic Commands

```
show environment temperature
show system resources
show fan status
```

Resolution Steps

- Step 1: {'Step': '1. Shut down the switch to prevent further damage.', 'Action': 'shutdown'}
- Step 2: {'Step': '2. Check the temperature and fan status using the show environment temperature and show fan status commands.', 'Action': 'show fan status'}
- Step 3: {'Step': '3. Replace the faulty component (CPU or fan) if necessary.', 'Action': 'replace CPU/fan'}
- Step 4: {'Step': '4. Reboot the switch after replacing the faulty component.', 'Action': 'boot'}
- Step 5: {'Step': '5. Verify the switch is functioning correctly using the show system resources command.', 'Action': 'show system resources'}

Post-Check Verification

```
show system resources
show environment temperature
show fan status
```