

Arista Access Switch Alarm 2724 Resolution Procedure

Node: Arista-Access-Mumbai-MH-36 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_2724

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve the critical alarm ALARM_2724 on the Arista Access Switch Arista-Access-Mumbai-MH-36.

Potential Root Causes

Cause	Probability
Arista EOS Software Crash	High
Hardware Faulty or Misconfigured	Medium
Incorrect Configuration	Low

Diagnostic Commands

```
show version
show system resource
show system internal routing
show interface | include errors
debug egress
show switch internal error
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Reboot the Switch', 'Action': "Reboot the Arista-Access-Mumbai-MH-36 switch using the command 'reload' and wait for it to come back online."}
- Step 2: {'Step': 'Step 2: Verify System Resources', 'Action': "Run the command 'show system resource' to verify that system resources are within normal limits."}
- Step 3: {'Step': 'Step 3: Check System Logs', 'Action': "Run the command 'show system internal error' to check for any system error messages related to the alarm."}
- Step 4: {'Step': 'Step 4: Verify Interface Configuration', 'Action': "Run the command 'show interface | include errors' to verify that there are no interface errors."}
- Step 5: {'Step': 'Step 5: Re-Configure the Switch', 'Action': 'Re-configure the switch using a known-good configuration file and verify that the alarm resolves.'}

Post-Check Verification

```
show version
show system resource
show interface | include errors
show system internal routing
```