

Arista Access Switch (Mumbai-MH-36) - Alarm Resolution SOP (ALARM_3413)

Node: Arista-Access-Mumbai-MH-36 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_3413

Description

This SOP outlines the steps to diagnose and resolve a critical alarm on the Arista Access Switch (Mumbai-MH-36) with alarm code ALARM_3413.

Potential Root Causes

Cause	Probability
Hardware Fault	High
Software Bug	Medium
Configuration Issue	Low

Diagnostic Commands

```
show system resource
show interface detail
show log | include ALARM_3413
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Check System Resources', 'Description': 'Verify if the system has sufficient resources (memory, CPU, etc.)', 'Commands': ['show system resource']}
- Step 2: {'Step': '2. Inspect Interfaces', 'Description': 'Verify interface status and configure settings', 'Commands': ['show interface detail']}
- Step 3: {'Step': '3. Analyze Logs', 'Description': 'Check log files for error messages related to the alarm', 'Commands': ['show log | include ALARM_3413']}
- Step 4: {'Step': '4. Collect Technical Support Data', 'Description': 'Collect system information and logs for further analysis', 'Commands': ['show tech-support']}
- Step 5: {'Step': '5. Reset or Replace Hardware (if hardware fault)', 'Description': 'Reset or replace the faulty hardware component', 'Commands': ['reset system', 'replace hardware component']}
- Step 6: {'Step': '6. Apply Software Patch (if software bug)', 'Description': 'Apply the latest software patch to resolve the issue', 'Commands': ['boot system sw-version 1.0.0']}

Step 7: {'Step': '7. Review Configuration', 'Description': 'Review and correct any configuration issues', 'Commands': ['show running-config | include ALARM_3413']}

Post-Check Verification

```
show system resource
show interface detail
show log | include ALARM_3413
```