

Arista Access Switch Alarm SOP - ALARM_3430

Node: Arista-Access-Mumbai-MH-36 | **Vendor:** Arista | **Severity:** Major | **Alarm Code:** ALARM_3430

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve a Major Alarm (ALARM_3430) on the Arista Access Switch Node ID: Arista-Access-Mumbai-MH-36.

Potential Root Causes

Cause	Probability
Hardware Failure in one of the Line Cards	High
Incorrect Configuration or Misconfiguration	Medium
Software Issues or Bug	Low

Diagnostic Commands

```
show system resource usage
show interface status
show switch resource usage
show logging | last 1000
```

Resolution Steps

- Step 1: {'Step': 'Verify system resource usage', 'Action': 'Check the output of show system resource usage for any signs of overload or misconfiguration.'}
- Step 2: {'Step': 'Verify interface status', 'Action': 'Check the output of show interface status for any indications of hardware failure or misconfiguration.'}
- Step 3: {'Step': 'Reboot the Switch', 'Action': '"Execute the command 'reboot' to reboot the switch and isolate the issue.'}"}
- Step 4: {'Step': 'Check Configuration', 'Action': 'Verify that the configuration is correct and not causing the issue.'}
- Step 5: {'Step': 'Check for Software Issues', 'Action': 'Check the software version and check for any known bugs or issues that may be causing the problem.'}

Post-Check Verification

```
show system resource usage
show interface status
```

```
show switch resource usage  
show logging | last 1000
```