

Standard Operating Procedure for Arista Access Switch Mumbai MH-44 - Alarm Code: ALARM_4847

Node: Arista-Access-Mumbai-MH-44 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_4847

Description

This SOP describes the steps to diagnose and resolve the Minor alarm ALARM_4847 on the Arista Access Switch Mumbai MH-44.

Potential Root Causes

Cause	Probability
Link Down on Port Channel	High
Spanning Tree Protocol Issue	Medium
Configuration Error	Low

Diagnostic Commands

```
show port-channel status
show spanning-tree detail
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Verify link status on port channel', 'Action': "Run the command 'show port-channel status' to check the link status on the port channel.", 'Command': 'show port-channel status'}
- Step 2: {'Step': 'Verify spanning tree protocol status', 'Action': "Run the command 'show spanning-tree detail' to check the spanning tree protocol status.", 'Command': 'show spanning-tree detail'}
- Step 3: {'Step': 'Verify configuration', 'Action': "Run the command 'show running-config' to check the configuration of the switch.", 'Command': 'show running-config'}
- Step 4: {'Step': 'Resolve configuration error', 'Action': 'Correct the configuration error and save the changes.', 'Command': 'no < incorrect configuration command>'}
- Step 5: {'Step': 'Reset spanning tree protocol', 'Action': 'Reset the spanning tree protocol to its default settings.', 'Command': 'spanning-tree reset'}
- Step 6: {'Step': 'Verify link up', 'Action': 'Verify that the link is up on the port channel.', 'Command': 'show port-channel status'}

Post-Check Verification

```
show port-channel status
show spanning-tree detail
show interface status
```