

Arista Access Switch Alarm Resolution SOP

Node: Arista-Access-Mumbai-MH-44 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM_7887

Description

This SOP outlines the steps to resolve Alarm ALARM_7887 on Arista Access Switch Node ID: Arista-Access-Mumbai-MH-44

Potential Root Causes

Cause	Probability
Interface Flapping	High
Misconfigured VLANs	Medium
Software Bug	Low

Diagnostic Commands

```
show interface status
show vlan
show version
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify interface status', 'Action': "Run command 'show interface status' to check for interface flapping", 'CLI_Commands': 'show interface status'}
- Step 2: {'Step': 'Check VLAN configuration', 'Action': "Run command 'show vlan' to check for misconfigured VLANs", 'CLI_Commands': 'show vlan'}
- Step 3: {'Step': 'Update software', 'Action': 'Update the software to the latest version if necessary', 'CLI_Commands': 'no shutdown'}
- Step 4: {'Step': 'Reset the interface', 'Action': 'Reset the interface to its default settings', 'CLI_Commands': 'interface GigabitEthernet1/0/1\n shutdown\n no shutdown'}

Post-Check Verification

```
show interface status
show vlan
show version
```