

SOP - Resolving ALARM_3601 on Arista-Access-Mumbai-MH-48

Node: Arista-Access-Mumbai-MH-48 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_3601

Description

This SOP outlines the steps to resolve the ALARM_3601 (Warning) alarm on Arista-Access-Mumbai-MH-48. The alarm indicates a potential issue with the switch's hardware or software.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Misconfigured Port	Low

Diagnostic Commands

```
show system resources
show environment
show interfaces status
show logging
debug hw-module switch 1
```

Resolution Steps

- Step 1: {'Step': '1. Verify the hardware health', 'Action': "Run the 'show system resources' and 'show environment' commands to check for any hardware issues."}
- Step 2: {'Step': '2. Check the port configuration', 'Action': "Run the 'show interfaces status' command to verify the port configuration. If the port is misconfigured, correct the settings."}
- Step 3: {'Step': '3. Check for software bugs', 'Action': "Run the 'show logging' command to check for any software-related issues. If a software bug is identified, contact Arista support for assistance."}
- Step 4: {'Step': '4. Perform a hardware reset', 'Action': "Run the 'hw-module switch 1 reset' command to perform a hardware reset. This may resolve the issue."}

Post-Check Verification

```
show system resources
```

```
show environment  
show interfaces status
```