

Arista Access Switch Mumbai Node (48)

ALARM_6885 Resolution SOP

Node: Arista-Access-Mumbai-MH-48 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_6885

Description

This SOP outlines the steps to diagnose and resolve a Critical ALARM_6885 on the Arista Access Switch Mumbai Node (48).

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Environmental Factors (e.g., power issues, temperature extremes)	Low

Diagnostic Commands

```
show system resources
show hardware
show environment
show version
show log messages | grep ALARM_6885
```

Resolution Steps

- Step 1: {'Step': '1. Identify the affected switch and verify the alarm status', 'Action': "Use the 'show system resources' and 'show log messages | grep ALARM_6885' commands to verify the alarm status."}
- Step 2: {'Step': '2. Perform a hardware inspection', 'Action': 'Physically inspect the switch and all connected components for any signs of damage or malfunction.'}
- Step 3: {'Step': '3. Check the software version and update if necessary', 'Action': "Use the 'show version' command to check the software version and update to the latest version if necessary."}
- Step 4: {'Step': '4. Check for environmental factors', 'Action': "Use the 'show environment' command to check for any environmental factors that may be contributing to the issue."}
- Step 5: {'Step': '5. Replace the affected hardware component (if necessary)', 'Action': 'If a hardware failure is identified, replace the affected component and verify the fix.'}

Post-Check Verification

```
show system resources  
show log messages | grep ALARM_6885  
show hardware
```