

Arista Access Switch ALARM_6050 SOP

Node: Arista-Access-Mumbai-MH-56 | **Vendor:** Arista | **Severity:** Critical | **Alarm Code:** ALARM_6050

Description

This SOP is designed to troubleshoot and resolve the critical alarm ALARM_6050 on the Arista Access Switch Node ID: Arista-Access-Mumbai-MH-56. The alarm indicates a critical issue that requires immediate attention.

Potential Root Causes

Cause	Probability
Hardware Failure: Power Supply Unit (PSU) failure	High
Software Bug: Misconfigured or faulty software image	Medium
Environmental Factors: Overheating, power outages, or electrical surges	Low

Diagnostic Commands

```
show system resources
show power
show environment
show log alarm
show system redundancy
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Power cycle the switch and verify if the alarm resolves', 'CLI_Commands': ['reload in 0', 'show system resources']}
- Step 2: {'Step': 2, 'Action': 'Replace the faulty PSU and verify if the alarm resolves', 'CLI_Commands': ['no power redundancy', 'show power', 'show system resources']}
- Step 3: {'Step': 3, 'Action': 'Reboot the switch in maintenance mode and verify if the alarm resolves', 'CLI_Commands': ['reload in 0 maintenance-mode', 'show log alarm']}
- Step 4: {'Step': 4, 'Action': 'Upgrade the software image to the latest version and verify if the alarm resolves', 'CLI_Commands': ['upgrade system software', 'show system resources']}

Post-Check Verification

```
show system resources
show log alarm
show system redundancy
```